



INFORMATION BULLETIN

No.001

TO : All CCS Lightning Dealers

DATE : April 10, 2006

SUBJECT : BATTERY CHARGER INSTALLATIONS

There have been several occurrences where the battery chargers have been mounted in a manner that is not a recommended installation procedure. The result is improper cooling of the battery charger leading to potential failures.

It is not recommended to install the battery charger in an horizontal upright position as illustrated. Customers should be advised to return to the installing dealer to correct the problem.

This repair is NOT covered under the CCS Lightning warranty.

