



INFORMATION BULLETIN

No.002

TO : All CCS Lightning Dealers

DATE : July 12, 2006

SUBJECT : **POWER DISTRIBUTION BOX**

There have been occurrences where Power Distribution Boxes have had flash codes 1-2-5-7 with no (or 1) flash code on the APU and the customer complaint will be that the air conditioner stops working when operating in high ambient temperatures.

If no faults with sensors or air conditioning can be found and the problem continues to repeat itself after clearing flash codes (done by removing the 7.5A ECU Battery Fuse - see fig. 2.1 page 22 of the Work Shop Manual), return Power Distribution Box to Mechtron for repairs.

