



LIGHTNING

SERVICE BULLETIN No.003

Circulate to listed addressees.

PRODUCT MODEL	: CCS Lightning
BULLETIN TYPE	: Product Correction
MANUAL / SECTION	: N/A
PARTS LIST REVISION	:
EFFECTIVE DATE	: November 10, 2005
SUBJECT	: ENGINE COOLANT HOSES
UNITS AFFECTED	: 20060-20119, 20245-20266, 20269, 20647, 20652-20654, 20679, 20688, 20691, 20692, 20694, 20697, 20698, 20701, 20703-20704, 20714, 20716-20718, 20721, 20728, 20729, 20734, 20745, 20747, 20748, 20762, 20769, 20773, 20781, 20785, 20789
PARTS AFFECTED	: 1060810 – Coolant hose, Outlet & 1060811 – Coolant hose, Inlet
TERMS & CONDITIONS	:

DESCRIPTION:

The APU coolant hoses may rub on the APU chassis. It is recommended that all serial numbers listed above be repaired.

Service personnel: Please read, initial and circulate.

Service Manager	Parts Manager	Warranty administrator	Workshop Foreman	Service Technician

PARTS AND PRODUCTS:

OLD PARTS:

PN:	Description:	Qty:
N/A		

NEW PARTS:

PN:	Description:	Qty:
#1060524	Split loom, 1" diameter, 6" per line	2
#1057994	Tie wrap, 5"	2

SYMPTOMS:

- Wearing of coolant hoses.
- APU has a possibility of coolant leak.

CORRECTION:

1. Install Split loom over coolant hoses.
2. Use tie's to secure in place.

