



LIGHTNING

SERVICE BULLETIN No.005

Circulate to listed addressees.

PRODUCT MODEL	: CCS Lightning
BULLETIN TYPE	: Product Correction
MANUAL / SECTION	: N/A
PARTS LIST REVISION	: 1064871-A
EFFECTIVE DATE	: April 5, 2006
SUBJECT	: Sticking Throttle Return Spring
UNITS AFFECTED	: Any unit with spring installed / No modifications
PARTS AFFECTED	: 1061352 Spring, Return
TERMS & CONDITIONS	:

DESCRIPTION:

The APU Throttle Return Spring may cause the APU Throttle to stick open. It is recommended that all APUs be repaired during regular service or if the APU fails to shut down.

Service personnel: Please read, initial and circulate.

Service Manager	Parts Manager	Warranty administrator	Workshop Foreman	Service Technician

PARTS AND PRODUCTS:

OLD PARTS:

PN:	Description:	Qty:
1061352	Spring, Return	1

NEW PARTS:

PN:	Description:	Qty:
N/A		

SYMPTOMS:

- APU will not shut down.

CORRECTION:

1. Remove 1061352 Spring, Return from 1061349 Lever, Engine Stop using a flat head screw driver.
2. Cut 1061352 Spring, Return using a pair of side cutter's or "dikes".

